	Туре	L #	Hits	Search Text	DBs	Time Stamp	Comments	ErrorDefinition	Er ro rs
1	BRS	L 1		(73/61.55-61.59).ccl s. or 210/656.ccls.	USPA T; EPO; JPO; DERW ENT	2002/12/0 3 20:28			Ο
2	BRS	L 6	82			2002/12/0 3 20:29			0
3	BRS	L 1 1	1	(slow\$3 or reduc\$5 or less\$5 or increas\$3 or great\$2 or fast\$3) with (flow\$5 or speed\$1 or velocit\$3) with pump\$3	USPA T; EPO; JPO; DERW ENT	2002/12/0 3 20:36			О
4	BRS	L 1 6	3	6 and 11	USPA T; EPO; JPO; DERW ENT	2002/12/0 3 20:39			0
5	BRS	L 2 6	0	21 not 16	USPA T; EPO; JPO; DERW ENT	2002/12/0 3 20:40			О
6	BRS	L 3 1	217	1 and 11	USPA T; EPO; JPO; DERW ENT	2002/12/0 3 21:21			0

	Туре	L #	Hits	Search Text	DBs	Time Stamp	Comments	E H H O H D O H H H H H O R	Errors
7	BRS	L 2 1	1	1 and 6		2002/12/0 3 20:42			0
8	BRS	L 3 6	0	6402946.URPN.	USPA T	2002/12/0 3 20:42			0
9	BRS	L 3 7	6	("5234586" "5283036" "5827946" "6090280" "6106710" "6139734").PN.		2002/12/0 3 20:42			0
10	BRS	L 3 8	0	31 and (micorvalve "micro valve")		2002/12/0 3 21:22			0
11	BRS	L 4 3	2	31 and (microvalve "micro valve")	USPA T; EPO; JPO; DERW ENT	2002/12/0 3 21:24			0
12	BRS	L 4 8	13	1 and (microvalve "micro valve")	USPA T; EPO; JPO; DERW ENT	2002/12/0 3 21:24			0